

Emcure

Pimpri-Pune

PEH-031/L2/01

EMCURE PHARMACEUTICAL LTD
Plot No. 12/1 &12/2, F-II Block, Pimpri-Pune.

MOCK DRILL REPORT

Type of Emergency	Electrical Panel short circuit, Fire & First Aid Injury
Date of Mock Drill	28 Oct 2025
Time of Mock Drill	20:26 Hrs
Location	BL - 2 MCC Room

A) Description of Scenario:

During routine operations in the BL-2 MCC Room, Mr. Akshay Malkhade suffered an electric shock and caught fire while working in the electric panel.

Nearby, Mr. Pravin Korde & Mr. Annasaheb Karande immediately noticed the incident and rushed to the scene. He retrieved a rescue stick to safely pull Mr. Akshay away from the electric panel. After checking for a response by pinching him and finding none, Mr. Pravin Korde promptly alerted the main gate via walkie-talkie, requesting an ambulance and the First Aid Team.

At the same time, Incident Controller Mr. Annasaheb Karande observed the fire in electric panel. Mr. Annasaheb Karande quickly located and used a CO₂ fire extinguisher to extinguish the flames.

Incident Controller, Mr. Annasaheb Karande, who immediately proceeded to the site accompanied by a departmental First Aid member. Mr. Annasaheb Karande also informed the Main Controller, Mr. Chetan Khariwale, about the situation. Main controller reached at Emergency Control Centre.

Meanwhile, Mr. Shubham Chougule and Mr. Sahil Tamboli assisted in transporting the victim to the Occupational Health Centre (OHC) for medical care.

Mr. Pravin Korde arrived at the OHC give first aid to Mr. Akshay. Once the victim's condition stabilized, the Incident Controller updated the Main Controller on the situation.

Teams involved in Mock Drill:

Sr. No	Team	Name of Employees
1	Safety Squad (Fire Fighting) Team	Mr. Annasaheb Karande, All Security guards
2	First Aid Team	Mr. Pravin Korde
3	Incident Controller	Mr. Annasaheb Karande
4	Main Controller	Mr. Chetan Khariwale

B) Mock Drill Observers:

Sr. No	Name of observer	Designation	Location
1	Mr. Mangesh Sonawane	Manager- EHS	Incident Spot & Assembly Point
2	Mr. Vilas Deshmukh	Executive – Pilot Plant	ECC

C) Observations (Details of time required for each activity).

Sr. No	Activity	Response Time (Min)		Time Taken
1	In the BL-2 MCC Room, Mr. Akshay Malkhade suffered an electric shock and caught fire while working in the electric panel.	20:26	20:26	10 Sec
2	Mr. Pravin Korde & Mr. Annasaheb Karande immediately noticed the incident and rushed to the scene. He retrieved a rescue stick to safely pull Mr. Akshay away from the electric panel. After checking for a response by pinching him and finding none	20:26	20:27	40 Sec
3	Mr. Annasaheb Karande observed the fire in electric panel. Mr. Annasaheb Karande quickly located and used a CO ₂ fire extinguisher to extinguish the flames	20:27	20:27	1 Min
4	Mr. Annasaheb Karande also informed the Main Controller, Mr. Chetan Khariwale, about the situation.	20:28	20:28	30 Sec
5	Mr. Shubham Chougule and Mr. Sahil Tamboli assisted in transporting the victim to the Occupational Health Centre (OHC) for medical care.	20:29	20:29	30 Sec

Emcure

Pimpri-Pune

PEH-031/L2/01

Sr. No	Activity	Response Time (Min)		Time Taken
6	Main controller reached at Emergency Control Centre.	20:26	20:27	1 Min
7	Mr. Pravin Korde arrived at the OHC give first aid to Mr. Akshay	20:30	20:30	1 Min
8	Main controller Mr. Chetan Khariwale gave instruction to safety squad team, to reach the incident spot.	20:27	20:28	1 Min
9	Incident controller report to main controller about situation under control by face to face communication.	20:28	20:29	1 Min
10	Security person inform to main controller about head count report. Total 16 person assembled & head count match accurately with gate entry register.	20:32	20:33	1 Min
11	Incident controller & Observer brief about incident and their observations to all employees.	20:33	20:35	2 Min

D) Suggestions / Recommendation:

Sr. No	Observations	Suggestions	Corrective action and compliance status	Responsibility	Compliance Status
1	Effective communication among the team member need to be improve.	Improve Proper Communication	We will ensure the same in future.	All employees	On going

mmj
03.11.2025
Prepared by

Olw
03.11.25
Approved By

Emcure

Pimpri-Pune

PEH-031/L2/01

E) Photographs

- 1. Mr. Akshay Malkhade was giving electric connection form BL-2 MCC room and got electric shock.**



- 2. Immediately nearby working Mr. Pravin Korde saw and rushed towards MCC panel room, brought rescue stick and pulled Mr. Akshay Malkhade**



3. Injured person shifted to OHC by using Stretcher & Wheelchair



4. First aid treatment given to Injured person in OHC



Emcure

Pimpri-Pune

PEH-031/L2/01

5. Emergency communication at ECC & extinguished the fire by using CO₂ type ext.



6. Incident controller, Main Controller & EHS head brief about incident and their efforts to control emergency.

